

0007

**SURFACE INSPECTION  
COMPLIANCE REPORT**Date of Inspection: November 22, 2000Case Serial No.: UTU-075888Operator: Resource Design Solution (RDS)Project Description: Mining GraniteLegal Description: SE¼ Sec 35, T. 12 S., R. 7 W.Field Office: FillmoreInspector: Larry Garahana**REPORT NARRATIVE (REFERENCE STIPULATIONS BY NUMBER OR TITLE)**

During this inspection I was accompanied by Tom Munson of Utah Division of Oil, Gas, and Mining (UDOGM). Also present was Joe Dunlop and Shayne Harris (Sawdust) of RDS. We were there to determine the size of this operation with the use of my GPS, and to discuss the plans for this site.

After walking the perimeter of the disturbance, we determined the size of this site to be 6.60 acres. At this time we discussed the options RDS had; they could reclaim down below five acres, or they could post a large bond with UDOGM, and submit a Plan of Operation/Large Mine Plan with us and UDOGM. RDS opted for reclaiming their site down below five (5) acres, and we (BLM, UDOGM, RDS) agreed that they would have this completed before the end of the calendar year (December 31, 2000).

During this inspection Sawdust stated that he would be able to work through the holiday weekend (Thanksgiving), and have this done in no time.

We'll continue to monitor this site for the changes and progress.

\_\_\_\_\_  
Signature of Inspector

\_\_\_\_\_  
Signature of Authorized Officer

0007